

IMPORTANT INFORMATION REGARDING A FEW PRODUCT PART NUMBERS



ANT-35000A
is now
ANT-35000A1



ANT-35000H
is now
ANT-35000H1



ANT-32000AS
is now
ANT-32000AS1

Please be aware that the following product part numbers are changing.

The digit 1 at the end of the previous part number signifies the first hardware change on the unit where we have been forced due to obsolescence to replace the HDMI IN/OUT chip.

There is no performance difference between devices having a letter or a letter and a digit 1 except for the following:

- 1) New Firmware has been developed for the A1 H1 and AS1 products that uses the last and latest firmware but adds support for this new HDMI chip.
- 2) The new firmware has all the features of previous versions except it adds support for the new HDMI chip.
- 3) Older A ,H and AS devices CAN use the new firmware going forward (and future updates) as the new firmware takes account of both old and new HDMI chips.
- 4) Old firmware however is NOT compatible with the New A1 H1 and AS1 devices.

The Version of Firmware to use with A1 and H1 (and all older devices is V3.802B02) Any number lower than V3.802 FW can only be used with A and H devices.

All future sales will be of the A1 H1 and AS1 devices

ANT-35000A	NOW	ANT-35000A1
ANT-35000H	NOW	ANT-35000H1
ANT-32000AS	NOW	ANT-32000AS1