








MARK	REASONABLE REVISIONS	REV. DATE	SIGN
①	-	-	-
②	-	-	-
③	-	-	-



NOTE
 1. Must remove harmful Burr.
 2. Assembling counterparts should be no abnormality.
 3. Apply general tolerances for unmarked tolerances.
 4. Mass production after obtaining approval.

1	-	-	-	-	-	-
No	NAME	Q'ty	ERP CODE	SPEC	MATERIAL	SUPPLY
PART NAME		DIMENSION		MATERIAL	END FINISH	
MODEL NAME		ANT-35100H		SUPPLY	SCALE	
PART NO & DRAWING NO		-		Q'TY	REV NO.	SIZE
DRAWN BY		CHECKED BY		APPROVED BY		MODIFIED BY
-		-		-		-
-		-		-		-



1 : 1 mm 1 / 1 A1